

SECTION: AG SERVICE BOARD

SUBJECT: GREAT PLAINS NO TILL DRILLS

Original Resolution No.: 08-02-10

Great Plains No Till Drill Policy

The Agricultural Service Board will retain one Great Plains No Till Seed Drill for use on County approved projects only.

The Great Plains No Till Seed Drill will be used on approved projects only using the following guidelines:

- Small Salinity Demo Plots
- Selected Watershed Recharge and Discharge Areas
- Special Projects as approved by the Ag Fieldman

Guidelines

1. The drills can only be used on land located within the boundaries of the County of Warner No. 5.
2. All arrangements for use are to be made through the Agricultural Service Board.
3. The renter shall indemnify and hold harmless the County of Warner No. 5, their employees and agents, from any and all liabilities, damages, costs, claims, or actions caused by or resulting from the rental and use of the pipeline plow.
4. The renter is responsible for any loss or damage to the plow while it is in their possession. It will be inspected by County of Warner No. 5 staff before and after each use to ensure any damage charges are assessed fairly.
5. A list of applicants will be kept and scheduling and distribution will be on a first come, first served basis or as near as is practical.
6. The drill will be cleaned and serviced by the producer using the drill.
7. The producer will provide the tractor (no less than 50hp and no greater than 150 hp) and a competent operator.
8. The drills will not be operated at speeds higher than 5 mph (8 km/hr)
9. It is the responsibility of the renter to familiarize themselves with the standard operating procedures and field operation and safety procedures provided to each renter in the handout manual.
10. Hookups will be made available, i.e. hydraulic adapters.

11. Signage and touring of the sites will be granted by the cooperator.
12. The producer agrees to pay the amount determined by the Agricultural Service Board within thirty (30) days.
13. Agricultural Service Board personnel will be responsible for dropping off and picking up the drills for the producer.